

NEW SITE IDENTIFICATION (NSI)

PART B - INEEL FFA/CO RESPONSIBLE PROGRAM MANAGERS (RPM'S) CONCURRENCE	
Site Title: 20" SW-NS-110477 Flange Leak East of CPP-601	Site Code: CPP-126
DOE-ID FFA/CO RPM Concurrence: <input type="checkbox"/> Concur with recommendation. <input checked="" type="checkbox"/> Do not concur with the recommendation.	
Signature: <u>Kathleen E. Hair</u>	Date: <u>5/24/05</u>
Explanation: <u>The site CPP-126 should be added to the FFA/CO but should be dispositioned in the DOB-14 ROD. If sufficient information is not available to support the 2008 ROD, then the site should be transferred to DO 10-08. No action is recommended based on current knowledge that only service waste flowed through the line.</u>	
EPA FFA/CO RPM Concurrence: <input type="checkbox"/> Concur with recommendation. <input checked="" type="checkbox"/> Do not concur with the recommendation.	
Signature: <u>[Signature]</u>	Date: <u>6-20-05</u>
Explanation: <u>See explanation above.</u>	
State of Idaho FFA/CO RPM Concurrence: <input type="checkbox"/> Concur with recommendation. <input type="checkbox"/> Do not concur with the recommendation.	
Signature: <u>Joyce J. Fink</u>	Date: <u>10/25/05</u>
Explanation: <u>I concur with DOE & EPA RPM's.</u>	

NEW SITE IDENTIFICATION (NSI)




Figure 1: Location of the flange leak.