

NEW SITE IDENTIFICATION

Part A – To Be Completed By Observer	
1. Person Initiating Report: Jacob Harris	Phone: 526-1877
Contractor WAG Manager: Douglas Burns	Phone: 526-4324
2. Site Title: 046, Test Apparatus West of CFA	
3. Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.	
An unknown test apparatus is located adjacent to West Portland Ave., 200yds west of CFA. During the July1999 site visit, the apparatus consisted of a square wooden structure sticking 8 inches out of the ground. Next to the wooden structure was a metal cabinet and a solar panel. Currently there is no electronics equipment in the metal cabinet and none of the visible wires appear to be connected. The GPS coordinates of the site are N683325.67 by E289939.04. The reference number for this site is 050 and can be found on the summary map as provided.	

Part B – To Be Completed By Contractor WAG Manager	
4. Recommendation:	
<input checked="" type="checkbox"/> This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO. WAG: 10 Operable Unit: 10-08	
<input type="checkbox"/> This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SHOULD NOT be included in the INEEL FFA/CO Action Plan.	
5. Basis for the recommendation:	
The conditions that exist at this site indicate the potential for an inactive waste site according to Section 2 of MCP-3448 Reporting or Disturbance of Suspected Inactive Waste Sites.	
The basis for recommendation must include: (1) source description; (2) exposure pathways; (3) potential contaminants of concern; and (4) descriptions of interfaces with other programs, as applicable (e.g., D&D, Facility Operations, etc.)	

6. Contractor WAG Manager Certification: I have examined the proposed site and the information submitted in this document and believe the information to be true, accurate, and complete. My recommendation is indicated in Section 4 above.		
Name: <u>Douglas E Burns</u>	Signature: <u>[Handwritten Signature]</u>	Date: <u>5/25/00</u>

NEW SITE IDENTIFICATION

Part C - To Be Completed By INEEL FFACO/CO WAG Managers

7. WAG Operable Unit:

DOE WAG Manager Concurrence: Concur with recommendation. Do not concur with the recommendation.

Signature: Patti Kroupa

Date: 5/3/00

EPA

EPA WAG Managers Concurrence: Concur with recommendation. Do not concur with the recommendation.

Signature: [Signature]

Date: 6/5/00

State of Idaho WAG Managers Concurrence: Concur with recommendation. Do not concur with the recommendation.

Signature: [Signature]

Date: 6-14-00

Explanation follows:

Part D - To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)

8. FFA/CO RPM's Concurrence:

For DOE-ID


Name: Kathleen Hain Signature: [Signature] Date: 7/12/00 Concur Do not concur. Explanation follows:

For EPA Region X

Name: Wayne Pierre Signature: [Signature] Date: 7/15/00 Concur Do not concur. Explanation follows:

For State of Idaho

Name: Dean Nygard Signature: [Signature] Date: 6/28/00 Concur Do not concur. Explanation follows:



MISC-46, Test Apparatus West of CFA