

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 2 INVESTIGATION OF
OPERABLE UNIT 3-07
08/10/99**

FILE NUMBER

ADMINISTRATIVE RECORD BINDER I

ARI.7 INITIAL ASSESSMENTS

- ▲ Document #: 5380
Title: CPP-16, Contaminated Soil from Leak in Line from CPP WM-181 to PEW
Author: N/A
Recipient: N/A
Date: 10/07/86

- ▲ Document #: 5384
Title: CPP-20, CPP-604 Radioactive Waste Unloading Area, OU 3-07
Author: N/A
Recipient: N/A
Date: 07/08/87

- ▲ Document #: 5388
Title: CPP-24, CPP Contaminated Soil in the Tank Farm Area
Author: N/A
Recipient: N/A
Date: 10/13/86

- ▲ Document #: 5389
Title: CPP-25, Contaminated Soil in Tank Farm Area North of CPP-604,
OU 3-07
Author: N/A
Recipient: N/A
Date: 10/13/86

- ▲ Document #: 5390
Title: CPP-26, Contaminated Soil in Tank Farm Area From Steam Flushing Operation, OU 3-07
Author: N/A
Recipient: N/A
Date: 10/13/86

- ▲ Document #: 5392
Title: CPP-28, Contaminated Soil in Tank Farm Area South of WM-181 by Valve Box A-6, OU 3-07
Author: N/A
Recipient: N/A
Date: 10/13/86

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 2 INVESTIGATION OF
OPERABLE UNIT 3-07
08/10/99**

FILE NUMBER

AR1.7 INITIAL ASSESSMENTS (continued)

- ▲ Document #: 5394
Title: **CPP-30**, Contaminated Soil in Tank Farm Area Near Valve Box B-9,
Author: N/A
Recipient: N/A
Date: 10/13/86
- ▲ Document #: 5395
Title: **CPP-31**, Contaminated Soil in Tank Farm Area South of Tank WM-183,
OU 3-07
Author: N/A
Recipient: N/A
Date: 10/13/86
- ▲ Document #: 5396
Title: **CPP-32**, Contaminated Soil in Tank Farm Area SW and NW of Valve Box B-4, OU 3-07
Author: N/A
Recipient: N/A
Date: 10/14/86

AR3.1 SAMPLING ANALYSIS PLANS

- ▲ Document #: RPO-047-92
Title: Transmittal of the Sampling and Analysis Plan for OU 3-07 at ICPP
Author: Lyle, J.L.
Recipient: Pierre, W.
Date: 03/02/92
- ▲ Document #: 4413
Title: **ICPP** Sampling and Analysis Plan for Operable Unit 3-07 Tank Farm Area
Author: WINCO
Recipient: N/A
Date: 02/28/92

AR3.9 QUALITY ASSURANCE PROJECT PLAN

- ▲ Document #: QAPJP-E-035
Title: Quality Assurance Project Plan for Characterization Activities at
WAG 3
Author: WINCO
Recipient: N/A
Date: 07/21/92

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 2 INVESTIGATION OF
OPERABLE UNIT 3-07
08/10/99**

FILE NUMBER

AR3.10 SCOPE OF WORK

▲ Document #: 5274
 Title: **Scope of Work** for the Track 2 Study of OU 3-07 Tank Farm 1
 Author: WINCO
 Recipient: N/A
 Date: 12/17/91

ADMINISTRATIVE RECORD BINDER II

AR3.11 FIELD SAMPLING

▲ Document #: 5516
 Title: Field Implementation Document
 Author: WINCO
 Recipient: **N/A**
 Date: 08/06/92

ADMINISTRATIVE RECORD BINDER III

AR3.14 TRACK 2 SUMMARY REPORT

▲ Document #: 5764
 Title: **Track 2 Summary Report** for Operable Unit 3-07
 Author: WINCO
 Recipient: N/A
 Date: 05/08/93

AR3.22 DECISION STATEMENT

▲ Document #: 5809
 Title: **Track 2 Decision Statement** for Operable Unit 3-07 Track 2 Summary Report
 Author: DOE-ID, EPA, IDHW
 Recipient: N/A
 Date: 10/26/94

AR7.7 NOTICE LETTERS AND RESPONSES

▲ Document #: AM/ERWM-RPO-202-92
 Title: **Notice of Delay** for Submission of 3-07 and 3-08 Summary Reports
 Author: Lyle, J.L.
 Recipient: Nygard, D., Pierre, W.
 Date: 09/28/92

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 2 INVESTIGATION OF
OPERABLE UNIT 3-07
08/10/99**

FILE NUMBER

AR12.3 RESPONSE TO COMMENTS

▲ Document #: RPO-091-92
 Title: **Transmittal** and Addendum for the Response to Comments for Draft SAP
 Author: Lyle, J.L.
 Recipient: Pierre, W.
 Date: 04/24/92

NOTE: Sampling data can be examined at the Technical Support Building, 1580 Sawtelle.